


5. Large impulse turbines will use what of rotor?						
A	Build-up rotors	B	Solid rotors.			
$(\mathbf{c}$	Combination of solid and build-up rotors.	D	All			
6. Tł	6. The most effect purging medium to use when dealing with iron sulphide is:					
A) air	B	carbon dioxide.			
$(\mathbf{c}$	nitrogen	D	water			
7. Tł	7. The shape of a ball bearing is when a load is applied to the ball.					
A	elliptical	B	circular			
$(\mathbf{c}$	rectangle	D	radial			
8. W	hich of the following is a typical 4000 hou	ır inspe	ection duty with compressors?			
A	Service the crankcase breather	B	Take oil samples			
\bigcirc	Recalibrate all temperature and pressure gauges	D	Check gas discharge and inlet temperatures			
9. W	hat does the term nominal filter refer to?					
A	A ratio of large to small particles found in a test run.	B	The largest particle that will pass through the filter under specific test conditions.			
C	 The length of time a filter is functional based on particle tests. 	D	That a stated percentage of a certain size particle will be stopped.			
10. W	hich of the following best defines a break	er fabr	ic?			
A	An open mesh used to reinforce against longitudinal breaking under impact	B	A single layer of fabric that provides load support			
0) The traverse yarns that run perpendicular to the warp yarns	D	Yarns in the fabric that provide the tension strength			



Referring to the figure, which of the following is a material section drawing for Bronze?

(A) 1	B 2
<u>С</u> з	D 4
E 5	F 6
G 7	H 8

1091. On a master precision level each division is sensitive to within _____ inch per foot on its main horizontal vial.

A	0.0005	В	0.05
(C)	0.005	D	0.5

1092. Which abbreviation stands for "cold rolled mild steel"?

(A)	MSCR	В	CRMS
(C)	RMSC	D	MSC

1093. In a refrigeration system the piping that connects the condenser to the receiver is called the:



A

(B) condensate drain line suction line (D) liquid line discharge line.

1094. When using the Explosive Actuated Tool process on steel a general recommendation is to drive the fasteners no closer than mm from another fastener

(A)	15	B	40
С	50	D	10

